

# Light report

09/13/2026

LOCATION DETAILS

Prepared by Demo inspector

1 reported location

TEST PREVIEW - simulated findings; not an actual inspection.

OFFICER COMMENTS

Demonstration only. Example fixture selection, not a maintenance request.

01

## Sandpiper Gatehouse

REPORTED ISSUE

Front: Front Building Light 1 out.

OBSERVATION RECORD

Reported: 2026-09-13  
Map location: 26.03286, -81.65527

# Light report

09/13/2026

LOCATION DETAILS

Prepared by Demo inspector

1 reported location

TEST PREVIEW - simulated findings; not an actual inspection.

01

## Sandpiper Gatehouse

CONTINUED / Front

FRONT

Entry into Fiddler's Creek  
Front Building Light 1 out.

Reference photo: Sandpiper Gatehouse / Front



PHOTO KEY Red: reported out / Gray: not reported out

|                                                                            |                                                                            |
|----------------------------------------------------------------------------|----------------------------------------------------------------------------|
| <div>1</div> <div>Front Facing Pillar 1</div> <div>Not reported out</div>  | <div>2</div> <div>Outside Pillar Light 1</div> <div>Not reported out</div> |
| <div>3</div> <div>Outside Pillar Light 2</div> <div>Not reported out</div> | <div>4</div> <div>Front Facing Pillar 2</div> <div>Not reported out</div>  |

Report reference: LUMEN-WEBSITE-DEMO.  
Dates record observations and do not prove uninterrupted failure.

# Light report

09/13/2026

LOCATION DETAILS

Prepared by Demo inspector

1 reported location

TEST PREVIEW - simulated findings; not an actual inspection.

01

## Sandpiper Gatehouse

CONTINUED / Front

5

**Front Building Light 1**  
REPORTED OUT

6

**Front Building Light 2**  
Not reported out

BACK

Exit out of Fiddler's Creek

No issues selected.

Reference photo: Sandpiper Gatehouse / Back



PHOTO KEY Red: reported out / Gray: not reported out

1

**Rear Building Light 1**  
Not reported out

2

**Rear Building Light 2**  
Not reported out

Report reference: LUMEN-WEBSITE-DEMO.  
Dates record observations and do not prove uninterrupted failure.

# Light report

09/13/2026

LOCATION DETAILS

Prepared by Demo inspector

1 reported location

TEST PREVIEW - simulated findings; not an actual inspection.

01

## Sandpiper Gatehouse

CONTINUED / Back

- 3

Rear Building Center Light

Not reported out
- 5

Side Pillar 2

Not reported out
- 7

Rear Facing Pillar 1

Not reported out
- 4

Side Pillar 1

Not reported out
- 6

Rear Facing Pillar 2

Not reported out

# Light report

09/13/2026

LOCATION DETAILS

Prepared by Demo inspector

1 reported location

TEST PREVIEW - simulated findings; not an actual inspection.

01

## Sandpiper Gatehouse

CONTINUED / Entry awning

ENTRY AWNING

Underside of the entry awning  
No issues selected.

Reference photo: Sandpiper Gatehouse / Entry awning




PHOTO KEY Red: reported out / Gray: not reported out

|                                                             |                                                             |
|-------------------------------------------------------------|-------------------------------------------------------------|
| <div>1</div> <div>Light 1</div> <div>Not reported out</div> | <div>2</div> <div>Light 2</div> <div>Not reported out</div> |
| <div>3</div> <div>Light 3</div> <div>Not reported out</div> | <div>4</div> <div>Light 4</div> <div>Not reported out</div> |

Report reference: LUMEN-WEBSITE-DEMO.  
Dates record observations and do not prove uninterrupted failure.

# Light report

09/13/2026

LOCATION DETAILS

Prepared by Demo inspector

1 reported location

TEST PREVIEW - simulated findings; not an actual inspection.

01

## Sandpiper Gatehouse

CONTINUED / Entry awning

|                                                             |                                                               |
|-------------------------------------------------------------|---------------------------------------------------------------|
| <div>5</div> <div>Light 5</div> <div>Not reported out</div> | <div>6</div> <div>Light 6</div> <div>Not reported out</div>   |
| <div>7</div> <div>Light 7</div> <div>Not reported out</div> | <div>8</div> <div>Light 8</div> <div>Not reported out</div>   |
| <div>9</div> <div>Light 9</div> <div>Not reported out</div> | <div>10</div> <div>Light 10</div> <div>Not reported out</div> |

# Light report

09/13/2026

LOCATION DETAILS

Prepared by Demo inspector

1 reported location

TEST PREVIEW - simulated findings; not an actual inspection.

01

## Sandpiper Gatehouse

CONTINUED / Exit awning

EXIT AWNING

Underside of the exit awning  
No issues selected.

Reference photo: Sandpiper Gatehouse / Exit awning



PHOTO KEY Red: reported out / Gray: not reported out

- 1

**Light 1**  
Not reported out
- 3

**Light 3**  
Not reported out

- 2

**Light 2**  
Not reported out
- 4

**Light 4**  
Not reported out

# Light report

09/13/2026

LOCATION DETAILS

Prepared by Demo inspector

1 reported location

TEST PREVIEW - simulated findings; not an actual inspection.

01

## Sandpiper Gatehouse

CONTINUED / Exit awning

|                                                             |                                                               |
|-------------------------------------------------------------|---------------------------------------------------------------|
| <div>5</div> <div>Light 5</div> <div>Not reported out</div> | <div>6</div> <div>Light 6</div> <div>Not reported out</div>   |
| <div>7</div> <div>Light 7</div> <div>Not reported out</div> | <div>8</div> <div>Light 8</div> <div>Not reported out</div>   |
| <div>9</div> <div>Light 9</div> <div>Not reported out</div> | <div>10</div> <div>Light 10</div> <div>Not reported out</div> |